1127

County Clerk's Certificate

The subdivider has complied with the following:
Road improvements have been installed in accordance with the requirement of these regulations and with the action of the Board of County Commissioners.

Silvano Romero by: R. C. Chavez Deputy
County Clerk - Rio Arriba County, N.M.

June 22 1981
Date

UNIT 6
EL VADO LAKE SUBDIVISION
TIERRA AMARILLA LAND GRANT
RIO ARRIBA COUNTY, NEW MEXICO
MAY 1981



VICINITY MAP


UNIT 1
UNIT 2
UNIT 3
UNIT 4
UNIT 7
UNIT 8
UNIT 9
N
1" = 400'
U.S.C.&G.S. BRASS CAP "DAM"
N84°57'19"W 12,975.57
N55°55'54"E 76.37
S47°42'58"E 861.87
S63°25'36"E 50.00
N03°19'22"E 303.61
S86°40'38"E 50.00
S86°40'38"E 1005.12
R=2419.43
L=161.42
S82°30'08"E 852.94
20' NORTHERN RIO ARRIBA ELECTRIC CO-OP EASEMENT
S89°15'09"W 927.65
S89°15'09"W 1000.00
N00°44'51"E 5609.87
S00°44'51"E 5609.87
N28°42'17"E 9962.22
N16°14'38"E 3290.85
N69°05'31"W 1170.88
S23°30'37"W 430.70
R=1427.86
L=284.05
N67°27'31"W 832.55
N71°12'52"W 1028.94
N59°45'36"W 50.00
R=43.78
L=55.04
S89°15'09"W 50.00
S00°44'51"E 125.50
N31°17'29"W 690.67
N73°45'22"W 587.26
N87°02'43"W 982.87
N69°52'28"W 809.63
S71°50'18"W 228.05
S79°40'13"E
S26°53'28"W
N69°12'43"W
N25°14'41"W
N89°16'54"W 811.87
S88°16'28"W 670.25
N85°44'33"W 989.15
N68°34'53"W
N84°52'33"W 856.47
S21°35'07"W 351.92
S27°39'40"E 403.39
S33°21'06"W 512.54
S79°38'26"E-CALLE-DE LOS-156.76
S39°18'28"E-COYOTES-799.48
S00°32'17"W 5.84
S00°44'51"E 258.71
S00°44'51"E 561.10
S00°44'51"E 435.60
S00°44'51"E 500.24
S00°44'51"E 499.82
S00°44'51"E 488.88
S00°44'51"E 444.41
S00°44'51"E 564.31
S00°44'51"E 427.15
S00°44'51"E 435.23
S00°44'51"E 291.87
S00°44'51"E 721.62
S00°44'51"E 1258.71
S00°44'51"E 1028.94
S00°44'51"E 1004.69
S00°44'51"E 1004.69
S00°44'51"E 500.00
S00°44'51"E 1000.00
S00°44'51"E 1000.00
S00°44'51"E 1000